

Kitchen Faucets

Two-Handle

Two-Handle

Product Name	Valve/Valvet [®]	Diverter	Aerator	Handle	Plug Button/ Cap	Sidespray	Other
Flair K-7765-8A K-7771-8A K-7776-8A K-7779-8A	GP77005-RP (H) GP77006-RP (C)	78444	41056* (2.2 gpm)	1000499-CP 50349-0L (Insert)	N/A	1021724* (Sidespray with Hose) 34329* (Holder)	See KOHLER.com/ ServiceParts
Forté [®] K-10445	Current GP1092204 (H) GP1092203 (C) 1990-2010 GP77005-RP (H) GP77006-RP (C)	GP75878	1031237* (2.2 gpm) Insert Options 1.5 gpm 1053334	See KOHLER.com/ServiceParts	N/A	1021724* (Sidespray with Hose) 1037431* (Holder)	See KOHLER.com/ ServiceParts
HiRise [®] K-7337 K-7341	GP77005-RP (H) GP77006-RP (C)	N/A	1069094* (2.2 gpm) Insert Options 1.5 gpm 1054424	See KOHLER.com/ServiceParts	N/A	N/A	See KOHLER.com/ ServiceParts
Parq [®] Bridge K-6130 K-6131	GP77005-RP (H) GP77006-RP (C)	GP75878	1088956 (1.8 gpm) Insert Options 1.5 gpm 1089003	See KOHLER.com/ServiceParts	N/A	1085211* (Sidespray with Hose/Holder)	See KOHLER.com/ ServiceParts
Purist [®] Bridge K-7547 K-7548	GP77005-RP (H) GP77006-RP (C)	GP75878	1074274 (1.8 gpm) Insert Options 2.2 gpm 1088956 1.5 gpm 1089003	See KOHLER.com/ServiceParts	N/A	1148477* (Spray/head) 1141915 (Hose) 1132472* (Holder)	See KOHLER.com/ ServiceParts
Revival [®] K-16109 K-16111	Current GP1092204 (H) GP1092203 (C) 1990-2010 GP77005-RP (H) GP77006-RP (C)	78444 GP75878	74405* (2.2 gpm) Insert Options 1.5 gpm 1054432	76153* 75143* 58742* 	N/A	1021724* (Sidespray with Hose) 34329* (Holder)	See KOHLER.com/ ServiceParts
Shoreham K-10900 K-10905	30393-RP (H) 30394-RP (C)	Discontinued	59619* (1.5 gpm)	58895-CP	N/A	1033012 (Sidespray with Hose) 1037431* (Holder)	See KOHLER.com/ ServiceParts
Taboret [®] K-8219 K-8220 K-8221	GP77005-RP (H) GP77006-RP (C)	78444	41056* (2.2 gpm)	See KOHLER.com/ServiceParts	N/A	1021724* (Sidespray with Hose)	See KOHLER.com/ ServiceParts

(H) = Hot (C) = Cold

*Include the color or finish code after the part number when ordering.